


Photo Portfolio

131 E. MAIN ST.
OTTUMWA, IOWA

2022 MOST ENDANGERED PROPERTY



First National Bank, Ottumwa, Iowa.


Front Corner (Ca. 1920)



Front Corner (Ca. 1965)



Front Corner (Current)



Front (Ca. 1916)




Front (Current)



Temple Front Details (Current)




Terra Cotta Spalling (Typical)



Rear (Current)



Side & Roof (Current)



First National Bank Lobby – Looking to Rear (Ca. 1916)



First Floor "Lobby" View – Looking to Rear (Before Cleaning)



Second Floor “Lobby” View – Looking to Rear (Before Cleaning)



Original Ceiling Details Above Drop Ceiling (Typical)



Exposed First Floor Tile (Typical)



Basement Debris & Water Inundation (Typical)